

Product Change Notification Form**PCN #:** 54-34-00021**Rev:** 1**Issue Date:** July 1, 2008**Type of Change:** EOL / Product Discontinuation**Detailed Description of Change:**

SSD 5000 1.8" UATA product line is discontinued.

Reason for change:

End of life (EOL) of 60nm flash

Products affected:

Part Number	Description	Last Time Buy	Last Time Shipment
SDU5B -032G-000000	SSD UATA 5000 1.8" 32GB	September 30 th , 2008	December 31 st , 2008
SDU5B-032G-102501	SSD UATA 5000 1.8" 32GB	September 30 th , 2008	December 31 st , 2008

Forecasted Key Milestones:

- Final order date (LTB): September 30th , 2008
- Final shipment date (LTS): December 31th , 2008

All orders subject to qualification and availability of 60nm material, and shall be accepted at SanDisk's sole discretion. For example, orders of the 60nm based product significantly in excess of forecasted demand or historical run rates may not be accepted.

Impact of Change and Recommended Action:

Customers using the SSD 5000 1.8" UATA are kindly requested to place orders before the last order date to ensure timely delivery

Reference Documents / Attachments:

None

Should you have any questions, please contact the Representative listed below within 10 days of this notice. No response will be deemed as customer's acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this PCN. We appreciate your cooperation with this matter.

Contacts:	Name	Email
Product Marketing Manager	Eyal bek	Eyal.bek@sandisk.com